

☐ SECRET

Approved For Release 2004/11/30 : CIA-RDP78B04770A000600040033-7

☒ CONFIDENTIAL

CIA-RDP78B04770A000600040033-7

☐ UNCLASSIFIED

☐ SECRET

DECLASSIFIED

CONTRACT INSPECTION REPORT			CONTRACT NO.		TASK NO.	
TO: ENGINEERING SECTION/CB/PD/OL			DATE 20 August 1965		2	
			INSPECTION REPORT NO. (If final, so state) 2			
			ESTIMATED COMPLETION DATE 30 December 1965			
NAME OF CONTRACTOR <div></div>						
TYPE OF COMMODITY OR SERVICE Modulated Light Direct Film Viewer						
THE CONTRACTOR IS ON SCHEDULE <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO			THE CONTRACTOR WILL PROBABLY REMAIN WITHIN ALLOCATED FUNDS <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO IF ANSWER IS "NO" ADVISE RECOMMENDATION AND/OR ACTION OF SPONSORING OFFICE, ON REVERSE HEREOF. IF KNOWN, INDICATE MAGNITUDE OF ADDITIONAL FUNDS INVOLVED.			
PER CENT OF WORK COMPLETED - 35%						
PER CENT OF FUNDS EXPENDED - 31%						
HAS AN INTERIM REPORT, FINAL REPORT, PROTOTYPE, OR OTHER END ITEM BEEN RECEIVED FROM THE CONTRACTOR DURING THE PERIOD? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (If yes, give details on reverse side.)						
HAS GOVERNMENT-OWNED PROPERTY BEEN DELIVERED TO CONTRACTOR DURING THIS PERIOD? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (If yes, indicate items, quantity, and cost on reverse side.)						
INCENTIVES						
IS THIS AN INCENTIVE CONTRACT IF YES, CHECK TYPE <input type="checkbox"/> COST <input checked="" type="checkbox"/> PERFORMANCE <input type="checkbox"/> DELIVERY			NOTE: USE REVERSE SIDE FOR COMMENTS. FINAL REPORT MUST CONTAIN INCENTIVE EVALUATION.			
OVERALL PERFORMANCE OF CONTRACTOR						
1. <input type="checkbox"/> OUTSTANDING 3. <input checked="" type="checkbox"/> ABOVE AVERAGE 5. <input type="checkbox"/> BELOW AVERAGE 7. <input type="checkbox"/> UNSATISFACTORY						
2. <input type="checkbox"/> EXCELLENT 4. <input type="checkbox"/> AVERAGE 6. <input type="checkbox"/> BARELY ADEQUATE						
IF OVERALL PERFORMANCE OF CONTRACTOR IS UNSATISFACTORY OR BARELY ADEQUATE, INDICATE REASONS ON REVERSE SIDE.						
RECOMMENDED ACTION						
<input checked="" type="checkbox"/> CONTINUE AS PROGRAMMED <input type="checkbox"/> WITHHOLD PAYMENT PENDING SATISFACTORY PERFORMANCE						
<input type="checkbox"/> TERMINATE <input type="checkbox"/> OTHER (Specify)						
IF TERMINATION IS RECOMMENDED OR IF THIS IS A FINAL REPORT PUT COMMENTS ON REVERSE IN NARRATIVE FORM ON CONTRACTOR'S PERFORMANCE AND CERTIFY THAT ALL DELIVERABLE ITEMS UNDER THE CONTRACT HAVE BEEN RECEIVED. THESE INCLUDE, WHERE APPLICABLE, THE FOLLOWING:						
ITEM		REC'D	DOES NOT APPLY	ITEM		
PROTOTYPES				MANUALS		
DRAWINGS AND SPECIFICATIONS				FINAL REPORT		
PRODUCTION AND/OR OTHER END ITEMS				SPECIAL TOOLING		
				OTHER GOVERNMENT PROPERTY		
DATE OF LAST CONTACT WITH CONTRACTOR 17 August 1965						
SIGNATURE OF INSPECTOR <div></div>			DIVISION P & D S			
INSPECTOR			SIGNATURE OF APPROVER			

Approved For Release 2004/11/30 : CIA-RDP78B04770A000600040033-7

☐ SECRET

☒ CONFIDENTIAL

☐ UNCLASSIFIED

Approved For Release 2004/11/30 : CIA-RDP78B04770A000600040033-7

NARRATIVE REPORT

☒ INTERIM

☐ FINAL

The first monthly progress report for the month of July 1965 was received 13 August 1965. (one copy attached)

Inspection visit of 16-17 August 1965



The meeting was begun with a general description of the progress to date; most of which is discussed in the first progress report. [] was told to consider using the Dynazoom Microscope in their design along with the ideas contained in both the [] studies.

The problems that were noticed are as follows:

1. With the present location of the film spools, loading is to be performed from the rear of the instrument. [] was told that this was undesirable and it is hoped that this design can be improved.
2. The pantagraph type microscope carriage protrudes past the rear of the instrument, and therefore the unit can not be pushed against a wall.
3. [] has not found a satisfactory material for flattening the faceplate. They are considering plastics.

The following items are to be supplied as part of the prototype:

1. Scope lock. This will allow the scope to be locked into position after it has been positioned.
2. The operator can locate the control box on either the left or right side.
3. A loading lamp will be included.
4. A storage drawer will be provided if space is available.

The knee space is now 23 inches high and 27 inches wide. The viewing surface height is 24 inches from the floor.

☐ UNCLASSIFIED

☒ CONFIDENTIAL

☐ SECRET